



## PLUMBING DIAGRAMMS




Fig 2.1 Engine Cooling inlet and winterizing/bilge pump valve




Figure 2.2 Raw water strainer. Aft Cabin - Picture taken from stern looking toward the engine





Fig 2.3 Accessory seawater seacock and manifold – general layout – Aft cabin looking toward the port quarter.




Fig 2.4 Accessory seawater intake system




Fig 2.5 Accessory seawater manifold






Figure 2.8 Potable water system – equipment mounted in the cabinet under the galley sink (photo taken from aft cabin looking forward – cabinet doors and horizontal shelf removed for picture)







Figure 2.8 Holding tank, Head direct overboard discharge, Macerator pump and seacock.





*Galina Yachts*

TROUGH HULL LOCATION 4.3.1